


## ToolMod Faderbox LINK INPUTS (CONTROL)



1 PFL LINK IN +

6 PFL LINK IN -

2 GROUND

7 GROUND

3 PFL CONTROL BUS

8 GROUND

4 SOLO BUS

9 LINK IN RELAY INPUT

5 +24 V FOR LINK IN RELAY

SubD-9 Connector  
Female in Console Frame

